


Suggested process----- FT-210 crimp with 18AWG wire instruction



20AWG wire--- Suggest stripping the wire insulation up to 3cm approx.